

# Work Order (Bid Form)

Richard Goddard 615-812-8955

## **WORK ORDER INFORMATION**

Work Order Name: WO/90009MD2624/1

Work Order Type: Weatherization

Audit Name: 90009MD2624

# **CLIENT INFORMATION**

Client Name: Address:

Client ID: 90009MD2624

Alt. Client ID: Davidson

#### **AGENCY INFORMATION**

Agency: Metropolitan Development and Housing Agency Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 Email Address:

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Audit Performed 21 March 12, Site built 1928, 1787 SQFT

Blower door reading = 6502@50PA - Target will be difficult to reach due to age and construction techniques of home. Kitchen and bath vents not installed due to low sloping roof over these rooms. Owner is aware that exterior walls will be drilled to install insulation and the it will be difficult to patch perfectly but is OK with that. She definitely wants the walls insulated.

Client Name:
Client ID: 90009MD2624
Alt. Client ID: Davidson

Work Order (Bid Form)

DOE Weatherization Assistant Version 8.6.0

Work Order Name: WO/90009MD2624/1 Report Run On: 3/21/2012

Page 1 of 7

ı	Measure 1	Seal	Ducts		(	Compone	nts			Inspected
C			ork- Mastic seal 9 boots d connectors in ductwo						III	
						Estimate	d		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneou	ıs Su	Duct Sealing	Each	1					
C	Other Detail									
					Measure	Sub Total:		] ;	Sub Total:	
	Field Notes:									
	comment Infi 1. ( 2. A Ins 3. A 4. S	Itratio Caulk Attic A ulate Attic A	ration Redctn In Reduction Measures plumbing penetrations Access - Provide new p Access - WS 2nd acces around chimney thru ce interior windows in fini	at kit sink anel (app 2 ss, insulate iling in finis	24x42") panel ( shed att	4" foam) ic	of square			Inspected
			ndows)			•				
					-	Estimate	d		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneou	ıs Su	Infiltration Reduction	Each	1					
C	Other Detail									
					Measure	Sub Total:		]	Sub Total:	
	Field Notes:									
L										

Measure 3 DV	VH Tank Insulation			Componen	ts			Inspected
Comment DWH	– Tank insulation 40 gal, t	all, electric						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	VH Pipe Insulation - Wrap first 5 ft at hot & co	old lines		Componen	ts			Inspected
	•	old lines		Componen Estimated			Actual	Inspected
	•	old lines <i>Unit</i> s	Qty	•		Qty		Inspected Total
Comment DWH	- Wrap first 5 ft at hot & co		<b>Qty</b> 1	Estimated		Qty	Actual	
Comment DWH	- Wrap first 5 ft at hot & co	Units		Estimated		Qty	Actual	
# Material / Labor  1 Insulation	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	<i>Units</i> Each	1	Estimated		Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	<i>Units</i> Each	1	Estimated		Qty	Actual	
# Material / Labor 1 Insulation 2 Labor	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	<i>Units</i> Each	1	Estimated			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	Units Each Each	1 1	Estimated			Actual	
# Material / Labor 1 Insulation 2 Labor	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	Units Each Each	1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor  1 Insulation  2 Labor  Other Detail	- Wrap first 5 ft at hot & co  Description / Comment  DHW Pipe Insulation	Units Each Each	1 1	Estimated Unit Cost			Actual Unit Cost	

#### Components WL1,WL10,WL2,WL Inspected **Measure 5** Wall Insulation 3,WL4,WL5,WL6,W L7, WL8, WL9 Comment Exterior Walls = masonite siding exterior, sheetrock interior. Owner is OK with drilling holes in exterior, patch as close as possible to existing and paint. **Estimated** Actual Material / Labor **Description / Comment Units** Qty **Unit Cost** Total Qty **Unit Cost Total** SqFt 1061 Insulation Wall Insulation -Cellulose, Blown - 2x4 Filled 2 Labor Wall Insulation -SqFt 1061 Cellulose, Blown - 2x4 Filled Other Detail Sub Total: Measure Sub Total: Field Notes: Measure 6 Storm Windows **Components** WD7 Inspected Comment Win7 = App 48x26 **Estimated** Actual # Material / Labor **Description / Comment Units** Qty **Unit Cost** Total Qty **Unit Cost Total** SqFt 8.667 Windows Storm Window Storm Window SqFt 8.667 Labor 3 Other Storm Window Each Window Other Detail

Field Notes:

Measure Sub Total:


Page 4 of 7

Sub Total:

Measure 7 CO	Monitor is Needed			Componen	ts			Inspecte
Comment								
			Estimated				Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
						] []		
			Measur	e Sub Total:		•	Sub Total:	
Field Notes:	ida CINAC Sikara (24.	201			4-			Inspects
Measure 8 Prov	ride 6 HVAC filters (24x	30)		Componen				Inspecte
Measure 8 Prov			Ofv	Estimated	1	Oftv	Actual	
Measure 8 Prov Comment # Material / Labor	ride 6 HVAC filters (24x  Description / Comment  Misc Material	Units Each	<b>Qty</b> 1	-		Qty		Inspecte Total
Measure 8 Prov Comment # Material / Labor	Description / Comment	Units	_	Estimated	1	Qty	Actual	
Measure 8 Prov Comment # Material / Labor O Unspecified	Description / Comment	Units	_	Estimated	1	Qty	Actual	
Measure 8 Province  Comment  Material / Labor  Unspecified	Description / Comment	Units	_	Estimated	1		Actual Unit Cost	
Measure 8 Prov Comment # Material / Labor O Unspecified	Description / Comment	Units Each	1	Estimated	1		Actual	
Measure 8 Prov Comment  # Material / Labor 0 Unspecified Other Detail	Description / Comment	Units Each	1	Estimated Unit Cost	1		Actual Unit Cost	
Measure 8 Prov Comment # Material / Labor 0 Unspecified	Description / Comment	Units Each	1	Estimated Unit Cost	1		Actual Unit Cost	

Actual Unit Cost	
	Total
ub Total:	
,	Inspect
	1
A -4	
Actual	Tata
Actual Unit Cost	Total
	L

Measure 11 Vap	or Barrier Needed			Componen	ts			Inspected
	apor barrier on ground ar 12" and seal)	nd 12" up	founda	ation wall &	secure, (	overlap		
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor	Remove and replace owners contents	Hour	3					
1 Health and Safety	Vapor Barrier Needed 6 Mil	SqFt	1387					
Other Detail				,				
			Measure	e Sub Total:		] ;	Sub Total:	
Field Notes:				-				
		Work O	rder Gra	nd Total:		Gran	d Total:	



Wall 1

North

